### 10/760583





Registered Patent Agents

Yasser Mourtada Kellie K. DiNapoli Julie L. Blum Cynthia L. DeRenzo Alyson C. Fuller

January 16, 2009

WRITER'S DIRECT NUMBER: (202) 772-8675 INTERNET ADDRESS: JHELVEY@SKGF.COM

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

For:

Art Unit 2611

Attn: Mail Stop Certificate of Correction

Re:

U.S. Utility Patent

Patent No. 7,460,585 B2; Issued: December 2, 2008

Methods and Systems for Detecting Defects in Serial Link

**Transceivers** 

Inventor: Pieter Vorenkamp Our Ref: 1875.4230001

Sir:

Transmitted herewith for appropriate action are the following documents:

- 1. Request for Certificate of Correction;
- 2. Certificate of Correction (Form PTO/SB/44); and
- 3. Return postcard.

It is respectfully requested that the attached postcard be stamped with the date of filing of these documents, and that it be returned to our courier.

In the event that extensions of time are necessary to prevent abandonment of this patent application, then such extensions of time are hereby petitioned.

EJAN 2 2 2003

Commissioner for Patents January 16, 2009 Page 2

The U.S. Patent and Trademark Office is hereby authorized to charge any fee deficiency, or credit any overpayment, to our Deposit Account No. 19-0036.

Respectfully submitted,

STERNE, KESSLER, GOLDSTEIN & FOX P.L.L.C.

Jeffrey T. Helvey Attorney for Patentee Registration No. 44,757

Jel Helm

JTH/tas Enclosure(s)

928173\_1.DOC



#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of:

Pieter Vorenkamp

Patent. No.: 7,460,585 B2

Issued: December 2, 2008

For: Methods and Systems for Detecting Defects in Serial Link Transceivers

Confirmation No.: 1121

Art Unit: 2611

Examiner: Vo, Don Nguyen

Atty. Docket: 1875.4230001

# Request for Certificate of Correction Under 37 C.F.R. § 1.322

Attn: Certificate of Correction Branch

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

It is hereby requested that a Certificate of Correction under 37 C.F.R. § 1.322 be issued for the above-captioned United States Patent. This Certificate of Correction is being requested due to mistakes which appear in the printed patent. These mistakes were made by the U.S. Patent and Trademark Office.

Specifically, the printed patent contains the following errors for which a Certificate of Correction is respectfully requested:

In Column 7, lines 12-14, "The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense alternating current provided by the common-mode control circuit." should read --The serial link transceiver according to claim 5, wherein the monitoring system comprises a voltage monitoring system.--

In Column 7, lines 16-18, "The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense direct current provided by the common-mode control circuit." should read --The serial link transceiver according to claim 1, wherein the monitoring system comprises a voltage monitoring system."

In Column 7, lines 19-22, "The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense alternating current and direct current provided by the common-mode control circuit." should read --The serial link transceiver according to claim 1, wherein the monitoring system comprises a current monitoring system.--.

In Column 7, lines 23-25, "The serial link transceiver according to claim 5, wherein the monitoring system comprises a voltage monitoring system." should read --The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense alternating current provided by the common-mode control circuit.

In Column 7, lines 26-28, "The serial link transceiver according to claim 1, wherein the monitoring system comprises a voltage monitoring system." should read --The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense direct current provided by the common-mode control circuit.

In Column 7, lines 29-31, "The serial link transceiver according to claim 1, wherein the monitoring system comprises a current monitoring system." should read --The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense alternating current and direct current provided by the common-mode control circuit.

#### Remarks

The above-noted corrections do not involve such changes in the patent as would constitute new matter or would require reexamination.

A completed Form PTO/SB/44 accompanies this request, with the above-noted corrections printed thereon. Accordingly, a Certificate of Correction is believed proper and issuance thereof is respectfully requested.

The Commissioner is hereby authorized to charge any fee deficiency, or credit any overpayment, to our Deposit Account No. 19-0036.

Respectfully submitted,

STERNE, KESSLER, GOLDSTEIN & FOX P.L.L.C.

Jeffrey T. Helvey Attorney for Patentee Registration No. 44,757

Date:

1/16/09

1100 New York Avenue, N.W. Washington, D.C. 20005-3934 (202) 371-2600 928145\_1.DOC

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number (Also Form PTO-1050)

### UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 2

PATENT NO: 7,460,585 B2

DATED:

December 2, 2008

INVENTOR(S): Pieter Vorenkamp

It is certified that error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below.

In Column 7, lines 12-14, "The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense alternating current provided by the common-mode control circuit." should read -- The serial link transceiver according to claim 5, wherein the monitoring system comprises a voltage monitoring system.--

In Column 7, lines 16-18, "The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense direct current provided by the common-mode control circuit." should read -- The serial link transceiver according to claim 1, wherein the monitoring system comprises a voltage monitoring system."

In Column 7, lines 19-22, "The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense alternating current and direct current provided by the common-mode control circuit." should read -- The serial link transceiver according to claim 1, wherein the monitoring system comprises a current monitoring system.--.

In Column 7, lines 23-25, "The serial link transceiver according to claim 5, wherein the monitoring system comprises a voltage monitoring system." should read --The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense alternating current provided by the common-mode control circuit.--

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Sterne, Kessler, Goldstein & Fox P.L.L.C. 1100 New York Avenue, NW Washington DC 20005-3934 Atty. Dkt. No. 1875.4230001

This collection of information is required by 37 CFR 1.322, 1.323 and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you are required to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 2 of 2

PATENT NO:

7,460,585 B2

DATED:

December 2, 2008

INVENTOR(S): Pieter Vorenkamp

It is certified that error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below.

In Column 7, lines 26-28, "The serial link transceiver according to claim 1, wherein the monitoring system comprises a voltage monitoring system." should read --The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense direct current provided by the common-mode control circuit.--

In Column 7, lines 29-31, "The serial link transceiver according to claim 1, wherein the monitoring system comprises a current monitoring system." should read --The serial link transceiver according to claim 6, wherein the current monitoring system is configured to sense alternating current and direct current provided by the common-mode control circuit.--

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Sterne, Kessler, Goldstein & Fox P.L.L.C. 1100 New York Avenue, NW Washington DC 20005-3934 Atty. Dkt. No. 1875.4230001

JAN 2 2 2009

This collection of information is required by 37 CFR 1.322, 1.323 and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you are required to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.